

**BUILDING SURVEY**

INSTITUTION LAURELTON CENTER DATE OF SURVEY May 15, 1995

BUILDING: No. 17 NAME Glover Hall DATE BUILT 1949

DESIGNED USE Client Housing

PRESENT USE Client Housing HANDICAPPED ACCESSIBLE-ELEVATOR

DESCRIPTION OF CONSTRUCTION Roof-asbestos shingles over wood frame;  
Exterior walls-stone; Interior Walls-tile and plaster; Foundation and  
Floors-concrete; Window air conditioning

GENERAL CONDITION OF BUILDING EXCELLENT V. GOOD GOOD FAIR POOR V. POOR  
 X

SIZE FLOOR	GROSS HEATED		GROSS UNHEATED		FLOOR TOTALS		AIR COND
	Sq. Ft.	Cu. Ft.	Sq. Ft.	Cu. Ft.	Sq. Ft.	Cu. Ft.	Sq. Ft.
	COL 1	COL 2	COL 3	COL 4	COL 5	COL 6	COL 7
GROUND/BASEMENT.	5721	57210			5721	57210	1663
1st. . . . .	5352	53520			5352	53520	1278
2nd. . . . .	5352	53520			5352	53520	1268
3rd. . . . .			5352	37464	5352	37464	
4th. . . . .	-----	-----					
5th. . . . .	-----	-----					
6th. . . . .	-----	-----					
7th. . . . .	-----	-----					
8th. . . . .	-----	-----					
<b>BLDG. TOTALS . . .</b>	<b>16425</b>	<b>164250</b>	<b>5352</b>	<b>37464</b>	<b>21408</b>	<b>201714</b>	<b>4209</b>

**REPAIRS OR CRITICAL REPAIRS OR RENOVATIONS REQU**

**CRITICAL**

NONE

**URGENT**

NONE

**DESIRABLE**

1. Replace existing windows with insulated
2. Central Air Conditioning.
3. Renovate Bathrooms (Modernize).
4. Replace rear porch roof.
5. Replace asbestos shingle roof.
6. Replace downspout and airway drains around building.

