100 Timmy Lane

BUILDING SURVEY

INSTITUTION LAURELTON CENTER			_ DATE OF	SURVEY _	May 15, 1995		
BUILDING: No. 16 NAME Ireland Hall DATE BUILT 1969							
DESIGNED USE	School Br	ilding					_
PRESENT USE Program Area HANDICAPPED ACCESSIBLE-ELEVATOR							
DESCRIPTION OF CONS	STRUCTION	"Stone and	concrete	: Rubber 1	lat roof		_
Total electric HVAC							
GENERAL CONDITION OF BUILDING EXCELLENT V. GOOD GOOD FAIR POOR V. POOR							
	GROSS HEATED		GROSS UNHEATED		FLOOR TOTALS		AIR COND
SIZE FLOOR	Sq. Pt.		Sq. Pt.		Sq. Ft.		
	COL 1		COL 3			COL 6	COL 7
GROUND/BASEMENT						237090	
lst					23709	237090	23709
2nd							
3rd							
4th							
5th							
6th							
7th							
8th							

REPAIRS OR CRITICAL REPAIRS OR RENOVATIONS REQUIRED:

CRITICAL

NONE

URGENT

NONE .

DESTRABLE

- 1. Renovate toilet areas to accommodate clients with adaptive devices and providing adequate privacy.
- 2. Replace electric heat with steam operated uni-vents.