

BUILDING SURVEY

INSTITUTION LAURELTON CENTER DATE OF SURVEY May 15, 1995

BUILDING: No. 06 NAME Edgett Hall DATE BUILT 1926

DESIGNED USE Client Housing

PRESENT USE Client Housing HANDICAPPED ACCESSIBLE-ELEVATOR

DESCRIPTION OF CONSTRUCTION Foundation-concrete; Roof-asphalt shingles over wood frame; Walls-stone and tile; Floors-concrete; Window air conditioning

GENERAL CONDITION OF BUILDING EXCELLENT V. GOOD GOOD FAIR POOR V. POOR
X

SIZE FLOOR	GROSS HEATED		GROSS UNHEATED		FLOOR TOTALS		AIR COND
	Sq. Ft.	Cu. Ft.	Sq. Ft.	Cu. Ft.	Sq. Ft.	Cu. Ft.	Sq. Ft.
	COL 1	COL 2	COL 3	COL 4	COL 5	COL 6	COL 7
GROUND/BASEMENT.	4795	47950			4795	47950	1592
1st.	4795	47950			4795	47950	2114
2nd.	4795	47950			4795	47950	2130
3rd.			4795	33565	4795	33565	
4th.							
5th.							
6th.							
7th.							
8th.							
BLDG. TOTALS . . .	14385	143850	4795	33565	19180	177415	5836

REPAIRS OR

CRITIC

NONE

URGEN

NONE

DESIR

1. Replace windows with insulatio
2. Central Air Conditioning.
3. Replace downspout and airway drains around build
4. Replace asphalt shingle roof.
5. Replace built up (flat) porch roof.
6. Renovate bathrooms (modernize)
7. Replace galvanized water piping.



Cottage No.7