

**BUILDING SURVEY**

INSTITUTION LAURELTON CENTER DATE OF SURVEY May 15, 1995

BUILDING: No. 23 NAME Idell Building DATE BUILT 1921

DESIGNED USE Laundry

PRESENT USE Canteen

DESCRIPTION OF CONSTRUCTION Foundation-concrete; Roof-asphalt shingles over wood frame; Window air conditioning

GENERAL CONDITION OF BUILDING EXCELLENT V. GOOD GOOD FAIR POOR V. POOR

- 2

SIZE FLOOR	GROSS HEATED		GROSS UNHEATED		FLOOR TOTALS		AIR COND
	Sq. Ft.	Cu. Ft.	Sq. Ft.	Cu. Ft.	Sq. Ft.	Cu. Ft.	Sq. Ft.
	COL 1	COL 2	COL 3	COL 4	COL 5	COL 6	COL 7
GROUND/BASEMENT.	2529	30348			2529	30348	
1st. . . . .	2529	30348			2529	30348	2529
2nd. . . . .	-----	-----					
3rd. . . . .	-----	-----					
4th. . . . .	-----	-----					
5th. . . . .	-----	-----					
6th. . . . .	-----	-----					
7th. . . . .	-----	-----					
8th. . . . .	-----	-----					
BLDG. TOTALS . . .	5058	60696			5058	60696	2529

**REPAIRS OR CRITICAL REPAIRS OR RENOVATIONS REQUIRED:**

**CRITICAL**

NONE

**URGENT**

NONE

**DESIRABLE**

1. Replace existing windows with insulated glass.