

BUILDING SURVEY

INSTITUTION LAURELTON CENTER DATE OF SURVEY May 15, 1995

BUILDING: No. 03 NAME Lorison Hall DATE BUILT 1918

DESIGNED USE Client Housing

PRESENT USE Closed

DESCRIPTION OF CONSTRUCTION Foundation-concrete; Roof-asphalt shingles over wood frame; Walls-stone and tile; Floors-concrete

GENERAL CONDITION OF BUILDING EXCELLENT V. GOOD GOOD FAIR POOR V. POOR
X

SIZE FLOOR	GROSS HEATED		GROSS UNHEATED		FLOOR TOTALS		AIR COND
	Sq. Ft.	Cu. Ft.	Sq. Ft.	Cu. Ft.	Sq. Ft.	Cu. Ft.	Sq. Ft.
	COL 1	COL 2	COL 3	COL 4	COL 5	COL 6	COL 7
GROUND/BASEMENT. . .	3801	38010			3801	38010	
1st.	3434	34340			3434	34340	
2nd.	3434	34340			3434	34340	
3rd.			3434	24038	3434	24038	
4th.	-----	-----					
5th.	-----	-----					
6th.	-----	-----					
7th.	-----	-----					
8th.	-----	-----					
BLDG. TOTALS . . .	10669	106690	3434	24038	14103	130728	

REPAIRS OR CRITICAL REPAIRS OR RENOVATIONS REQUIRED.

CRITICAL

NONE

URGENT

NONE

DESIRABLE

1. Replace asphalt shingle roof.
2. Exterior and Interior need painted.
3. Asphalt floor tile need replaced.

