

**BUILDING SURVEY**

INSTITUTION LAURELTON CENTER DATE OF SURVEY May 15, 1995

BUILDING: No. 20 NAME Mary M. Wolfe Building DATE BUILT 1937

DESIGNED USE Offices, Living Quarters, Storage, Garage

PRESENT USE Offices, Living Quarters, Storage, Garage 1st FLOOR CHAIR LIFT

DESCRIPTION OF CONSTRUCTION Foundation-concrete; Roof-slate over steel and concrete; Walls-stone and tile; Floors-concrete; Window air conditioning

GENERAL CONDITION OF BUILDING EXCELLENT V. GOOD GOOD FAIR POOR V. POOR  
Z

SIZE FLOOR	GROSS HEATED		GROSS UNHEATED		FLOOR TOTALS		AIR COND
	Sq. Ft.	Cu. Ft.	Sq. Ft.	Cu. Ft.	Sq. Ft.	Cu. Ft.	Sq. Ft.
	COL 1	COL 2	COL 3	COL 4	COL 5	COL 6	COL 7
GROUND/BASEMENT.	11743	117430			11743	117430	1029
1st.	7712	77120			7712	77120	2832
2nd.	7712	77120			7712	77120	2350
3rd.	7712	77120			7712	77120	
4th.	7457	74570			7457	74570	
5th.	4289	55562	3168	19008	7457	74570	
6th.	-----	-----					
7th.	-----	-----					
8th.	-----	-----					
BLDG. TOTALS . . .	46625	478922	3168	19008	49793	497930	6211

**REPAIRS OR CRITICAL REPAIRS OR RENOVATIONS REQUIRED:**

**CRITICAL**

NONE

**URGENT**

NONE

**DESIRABLE**

1. Replace existing windows with insulated windows.
2. Replace slate shingle roof.
3. Central air conditioning.
4. Replace floor covering.

