

BUILDING SURVEY

INSTITUTION LAURELTON CENTER DATE OF SURVEY May 15, 1995

BUILDING: No. 25 NAME Snyder Building DATE BUILT 1928

DESIGNED USE Food Preparation, Storage, Dining Area

PRESENT USE Food Preparation, Storage, Central Storeroom

DESCRIPTION OF CONSTRUCTION Foundation-concrete; Roof - spray foam and stones over asphalt on concrete deck and steel frame; Walls - stone and tile; Floors concrete.

GENERAL CONDITION OF BUILDING EXCELLENT V. GOOD GOOD FAIR POOR V. POOR
X

SIZE FLOOR	GROSS HEATED		GROSS UNHEATED		FLOOR TOTALS		AIR COND
	Sq. Ft.	Cu. Ft.	Sq. Ft.	Cu. Ft.	Sq. Ft.	Cu. Ft.	Sq. Ft.
	COL 1	COL 2	COL 3	COL 4	COL 5	COL 6	COL 7
GROUND/BASEMENT.	14411	172932			14411	172932	5055
1st.	14246	170952			14246	170952	464
2nd.	2352	23520			2352	23520	1384
3rd.	-----	-----					
4th.	-----	-----					
5th.	-----	-----					
6th.	-----	-----					
7th.	-----	-----					
8th.	-----	-----					
BLDG. TOTALS . . .	31009	367404			31009	367404	6903

BUILDING SURVEY

INSTITUTION LAURELTON CENTER DATE OF SURVEY May 15, 1995

BUILDING: No. 26 NAME Snyder Building Annex DATE BUILT 1951

DESIGNED USE Refrigeration, Bakery, Milk Processing and Storage

PRESENT USE Refrigeration, Storage, and Custodial Office

DESCRIPTION OF CONSTRUCTION Spray foam and stone over asphalt roof; Roof deck concrete on steel; Exterior Walls - Stone; Interior Walls - Tile and Plaster; Foundation and Floors - Concrete

GENERAL CONDITION OF BUILDING EXCELLENT V. GOOD GOOD FAIR POOR V. POOR
X

SIZE FLOOR	GROSS HEATED		GROSS UNHEATED		FLOOR TOTALS		AIR COND
	Sq. Ft.	Cu. Ft.	Sq. Ft.	Cu. Ft.	Sq. Ft.	Cu. Ft.	Sq. Ft.
	COL 1	COL 2	COL 3	COL 4	COL 5	COL 6	COL 7
GROUND/BASEMENT.	5140	66820			5140	66820	952
1st.	3189	41457			3189	41457	
2nd.			3189	41457	3189	41457	
3rd.	-----	-----					
4th.	-----	-----					
5th.	-----	-----					
6th.	-----	-----					
7th.	-----	-----					
8th.	-----	-----					
BLDG. TOTALS . . .	8329	108277	3189	41457	11518	149734	952