

BUILDING SURVEY

INSTITUTION LAURELTON CENTER DATE OF SURVEY May 15, 1995

BUILDING: No. 44 NAME Superintendent's Residence DATE BUILT 1927

DESIGNED USE Superintendent's Residence

PRESENT USE Group Home

DESCRIPTION OF CONSTRUCTION Foundation-concrete; Roof-asbestos shingles over wood frame; Walls-stone; Floor-wood frame

GENERAL CONDITION OF BUILDING EXCELLENT V. GOOD GOOD FAIR POOR V. POOR
X

SIZE FLOOR	GROSS HEATED		GROSS UNHEATED		FLOOR TOTALS		AIR COND
	Sq. Ft.	Cu. Ft.	Sq. Ft.	Cu. Ft.	Sq. Ft.	Cu. Ft.	Sq. Ft.
	COL 1	COL 2	COL 3	COL 4	COL 5	COL 6	COL 7
GROUND/BASEMENT.	1993	19930			1993	19930	
1st.	1993	19930			1993	19930	
2nd.	1993	19930			1993	19930	
3rd.			1993	13951	1993	13951	
4th.	-----	-----					
5th.	-----	-----					
6th.	-----	-----					
7th.	-----	-----					
8th.	-----	-----					
BLDG. TOTALS . . .	5979	59790	1993	13951	7972	73741	

REPAIRS OR CRITICAL REPAIRS OR RENOVATIONS REQUIRED:

CRITICAL

NONE

URGENT

NONE

DESIRABLE

NONE

